


WAX MELTING FURNACE INSTRUCTIONS



FC

CE

UK
CA



NO.3

CONTENTS

I. English (For US, UK, Canada, Europe)	2
WARNINGS	2
PRODUCT OVERVIEW	4
PREPARATION	5
CANDLE MAKING STEPS	6
TROUBLESHOOTING	8
PRODUCT CIRCUIT DIAGRAM	8
Q&A	9
LEGAL DISCLAIMER NOTICE	10
SPECIFICATION	11
II. Język polski	12
OSTRZEŻENIA	13
OPIS PRODUKTU	15
PRZYGOTOWANIE	16
KROKI TWORZENIA ŚWIEC	17
ROZWIĄZYWANIE PROBLEMÓW	19
SCHEMAT OBWODU PRODUKTU	19
PYTANIA I ODPOWIEDZI (Q&A)	20
ZASTRZEŻENIE PRAWNE	22
SPECYFIKACJA	23

WARNINGS


- Before use, please check whether the power supply voltage is stable, whether the socket is stable and connected to the ground wire.
- Please add wax blocks or wax beans before use. The wax material needs to be at least 2cm deep from the bottom, and the maximum cannot exceed the MAX scale line.
- If the heating indicator (red light) is on, it means it is working; if it is green, it means it is using residual temperature heating. The yellow light indicates that it is in the keep warm state.
- It should be used indoors, and it should be used indoors where the ambient temperature is higher than 0°C or lower than 30°C, so as to avoid potential safety hazards such as freezing or equipment failure due to freezing.
- After use, please pour out the remaining wax completely. It is not recommended to store the wax overnight to prevent the wax liquid from solidifying and fouling, which will affect the heating function of the heating tube in the gallbladder.
- The connection method of the power cord of this unit, if the power cord is damaged, it must be replaced by the manufacturer, maintenance department or professionals to avoid danger. When using the power cord, the YZW type of oil-resistant sheathed flexible cable must be selected. The conductor area is 1.5-2.5sqmm.
- As the device is IPx3, do not use wax spray to clean the device.
- This wax melter is a heating product, and the surface will be hot during work. It is forbidden to directly touch the outer wall of the machine during and after work, and high temperature gloves must be worn during the whole process of work.
- Our wax melter have circuit protection system. Because wax is solid at room temperature, it has no fluidity. During the heating process, the bottom melts first, in order to prevent the bottom wax from being burned out by high temperature.

English

We design a temperature-sensing probe at the bottom. When it detects that the bottom temperature reaches the set temperature, it will automatically cut off the power supply and use the residual heat to continue to melt the wax. When it detects that the temperature is lower than the set temperature, it will automatically heat up.

- It is forbidden to disassemble the product without permission and change the circuit. Use electronic components other than this product instead. It is easy to cause a short circuit of the machine.
- Keep away from children, pets and plants during the working process of the wax melting furnace.
- The faucet has a heating core, and the surface will be hot when working. It is forbidden to directly touch the metal part of the faucet with your hands during and after work to prevent burns.
- In order to ensure the safe installation and normal use of the wax melting furnace, the bottom plate of the cabinet (where the wax melting furnace is used) must be smooth and flat, and the bottom must be fixed to prevent the wax liquid from being unbalanced and dumping accidents.
- Because the temperature sensor is installed at the bottom of the heating plate, there will be a temperature difference of $\pm 10^{\circ}\text{C}$ in the melter.

PRODUCT OVERVIEW




Free temperature setting
50-100°C/122-212°F

PREPARATION

1.Note:

(1)The machine must be used indoors and should be placed on a stable platform or bracket, and the trunk should be more than 10 cm away from the wall. Stay away from walls.



(2)Please do not turn on the power without adding candles, as this will cause damage to the machine or cause other hazards



(3)Because the candle has no fixed melting point, you need to set the corresponding heating temperature according to your candle type and melting point, otherwise the temperature will be too high and the candle will burn

(4)Cover the lid when using to avoid burns.

(5)The protection level of this machine for contacting live parts is Class I. The power plug must be equipped with a three-hole socket electrode with reliable protective grounding) and residual current circuit breakers with full-stage shutdown.



2.Indicator Explanation

Red light (Heating): Maching is heating.
Yellow light (Insulation): Machine is in keep warm state. When the temperature gets lower, the machine will heat up automatically.

Green light (Standby): Machine automatically cuts off the power and use the residual heat to continue to melt the wax.



CANDLE MAKING STEPS

1. Plug in the power cord, and turn on the switch. Check that the red light is normal enough. Then turn off the machine switch. Make sure there is no moisture in the furnace.



2. Wear gloves and work protection. During use, it is forbidden to wear short-sleeved shorts and skirts, and keep away from children and animals.



3. Put the wax into the wax melting furnace.

Note: at least it needs to exceed the bottom 2cm deep, and the maximum cannot exceed the MAX scale line.

4. Turn on the power switch and set the temperature to 5-10°C higher than the melting point of the wax.

Eg: Beeswax melting point is 62-67°C. Set heating temperature at 70°C.



5. The machine starts heating. During heating process, please cover the lid, and every 30-50s stir wax with a spoon for 3-4s.



6. During heating, in order to prevent the wax from being burned out due to high temperature, the machine will stop heating intermittently and use the residual heat to melt the wax. When the temperature is too low, the machine will heat up automatically

English

7. When the wax is all melted, turn off the power. Use a measuring cup or wax mold to pour the wax liquid from the machine faucet.



8. If you want your candle to have a more pleasant scent, you can add scented oils.



9. If you need more colorful candles, you can add dried flowers or dyes to your liking. After that, it can be demolded after 24 hours.(note: please do not use too much force when demoulding because the wax is not completely dry).



10. Machine leisure time:

When the machine is not in use, please turn off the faucet of the machine, disconnect the power supply, and place the machine in a dry environment at room temperature.


11. Kind tips :

After the wax is melted, it should be poured out in time to make a finished product, otherwise it will change color after a long time and affect the effect.

TROUBLESHOOTING

FAULT PHENOMENON	CAUSE OF ISSUE	ELIMINATION METHOD
Light does not shine	1. The indicator light is damaged 2. The indicator light circuit is disconnected	1. Replace the indicator light 2. Repair the disconnected line
Heating indicator light is on and the wax temperature does not rise	Phase loss of power supply or blown fuse	1. Replace the thermostat 2. Connect the ground wire
When the wax temperature reaches the set temperature, the work light does not go out	Thermostat damaged	Replace the thermostat
The body has induced voltage	Ungrounded wire or poor ground wire contact	Connect the ground wire

PRODUCT CIRCUIT DIAGRAM



Q & A

Q:How to clean the wax melter?

- A:1.Simple cleaning: After use, use a clean towel to wipe all the wax in the bucket before it solidifies. (Caution is required during operation to prevent burns).
- 2.After the wax liquid is completely poured out, fill the bucket with water (do not exceed the Max limit), turn on the power switch, and adjust the temperature of the thermostat to 70 degrees. After reaching the set temperature please turn off the power and start cleaning. Add an appropriate amount of citric acid or white vinegar to the wax melting furnace, put in a wiping cloth, stir with a wooden stick, clean the barrel wall and the bottom of the barrel, and drain the water from the faucet, then use a dry towel to clean the barrel wall and the barrel. When the bottom of the bucket is dry, close the lid, put the machine away, and wait for the next use. (Please wear high temperature gloves during the entire cleaning process, Prevent burns, and be careful not to let the machine Be dumped).

Q:How much soy wax can be melted at the time?

- A:WMF-5L: It can melt up to 1.65KG at one time (70% of the maximum capacity);
WMF-8L: Can melt up to 3.5KG at one time (70% of the maximum capacity)
WMF-15L: It Can melt up to 7KG at one time (70% of the maximum capacity)

Q: Can the melted wax be stored in the wax melter?

- A: It is not recommended to store the wax overnight to prevent the wax liquid from solidifying and fouling, which will affect the heating function of the heating tube in the gallbladder. If the remaining wax solidifies in the wax melter, the wax melting furnace has been upgraded with an anti-dry burning protection system and a heating core faucet to prevent that wax over burning and clogged faucet.

Note:when the wax solidified in the wax melter and need to melt again, the melting time will be prolonged.

Q: During use, why the heating light (Heating) turns to the green light (Standby) before the wax has melted automatically?

- A: In order to prevent the wax over burning, with upgraded anti-dry burning protection system. Once the melter bottom temperature reach the setting temperature, the controller will automatically turn to the stop heating mode and use the residual temperature to melt the wax. Waiting for few minutes and it will heat up again and turn on the red light (Heating) again.

LEGAL DISCLAIMER NOTICE

1. Please wear protective equipment during working process to prevent burns.
2. Website pictures for reference only, specific products in kind prevail. The products of distribution channels in different regions will be slightly different, and the products displayed in the mall shall prevail.
3. The product packaging pattern will be changed without notice, and the pictures in the mall will be updated as much as possible to ensure the latest product types.
4. Our wax melter certified CE , FCC ,RoHS, UKCA, its normal there is wax smell when melting wax beans.
5. It is forbidden to disassemble the internal circuits and components of this product without permission, or replace non-company components, otherwise the company will not be responsible for the damage of the product.
6. For all products sold, this site first requires that on the premise of strictly using assembly and necessary model technology, we are only responsible for the after-sales of the product (the purchased product itself) (when repaired or replaced)
The manufacturer confirms that it is The company is not responsible for any quality problems, any other loss or damage.
7. Necessary knowledge and advice from others. We strongly recommend that all buyers must learn some basic knowledge of using the machine installation and debugging, and then use it under the personal guidance of experienced enthusiasts.
8. The machine must be used in a stable and fixed place, the machine must be kept from falling danger, and the machine must be kept away from children and pets when using the machine.
9. The product is only a legal device. Without the written consent of the manufacturer and sales agent, no one may use the sample product for other commercial channels. Do not use it for political, religious, military or other special and illegal purposes.
10. As a product of melting wax, the design, manufacture and sale of the manufacturer are not mixed with any propaganda meaning of politics, military, religion, country, race or skin color. The manufacturer's purpose is to respect science, abide by historical rules, and uphold human peace.

SPECIFICATION

Model	WMF-5L	WMF-8L	WMF-15L
Capacity	5L	8L	15L
Rated Voltage	AC 120V; 60HZ (The United States)		
	AC 230V; 50HZ (United Kingdom/Germany)		
Bucket Material	Stainless Steel		
Rated power	1100W		
Temperature range	50°C-100°C(122°F-212°F)		


Friendly reminder: The voltage(AC 120V/60Hz or AC 230V/50Hz) of the product depends on your order.

4.WEEE disposal logo:

The product complies with the requirements of the Waste Electrical and Electronic Equipment (WEEE) Directive and strictly complies with the relevant regulations.



INSTRUKCJA PIECA DO TOPIENIA WOSKU



FC

CE

UK
CA



NO.3


OSTRZEŻENIA

- Przed użyciem sprawdź, czy napięcie zasilania jest stabilne, czy gniazdko jest stabilne i podłączone do przewodu uziemiającego.
- Dodaj bloki wosku lub granulki wosku przed użyciem. Wosk powinien znajdować się co najmniej 2 cm nad dnem urządzenia, a maksymalna ilość wosku nie powinna przekraczać linii maksymalnego poziomu (MAX).
- Jeśli wskaźnik grzania (czerwone światło) jest włączony, urządzenie działa. Jeśli świeci się zielone światło, oznacza to, że urządzenie korzysta z pozostałego ciepła. Żółte światło wskazuje, że urządzenie znajduje się w stanie podtrzymywania ciepła.
- Urządzenie należy używać wewnątrz pomieszczeń i w temperaturze otoczenia wyższej niż 0°C oraz niższej niż 30°C, aby uniknąć potencjalnych zagrożeń bezpieczeństwa, takich jak zamarzanie lub uszkodzenie urządzenia z powodu niskiej temperatury.
- Po użyciu wylej całkowicie pozostały wosk. Nie zaleca się przechowywania wosku w urządzeniu na noc, aby zapobiec jego zestaleniu i zabrudzeniu, co może wpłynąć na funkcję grzewczą urządzenia.
- Jeśli przewód zasilający urządzenia jest uszkodzony, należy go wymienić u producenta, w serwisie lub przez wykwalifikowanego specjalistę, aby uniknąć zagrożeń. W przypadku wymiany należy użyć przewodu YZW odpornego na wysoką temperaturę. Powierzchnia przekroju przewodu powinna wynosić 1,5–2,5 mm².
- Urządzenie jest zgodne z klasą ochrony IPX3. Nie używaj sprayów z woskiem do czyszczenia urządzenia.
- Podgrzewacz wosku to urządzenie grzewcze, a jego powierzchnia podczas pracy jest gorąca. Zabrania się dotykania zewnętrznych ścian urządzenia w trakcie lub po pracy. W trakcie korzystania z urządzenia należy nosić rękawice ochronne.
- Urządzenie posiada system ochrony obwodów. Ponieważ wosk w temperaturze pokojowej jest w stanie stałym, urządzenie nie uruchomi się bez wosku. W trakcie podgrzewania dno urządzenia nagrzewa się najpierw, aby zapobiec spaleniu się wosku na dnie pod wpływem wysokiej temperatury.

Zapewniamy projekt sondy do pomiaru temperatury umieszczonej na spodzie urządzenia. Gdy wykryje, że temperatura dna osiągnęła ustawioną wartość, automatycznie odcina zasilanie i wykorzystuje pozostałe ciepło do kontynuacji topienia wosku. Gdy wykryje, że temperatura jest niższa od ustawionej, automatycznie wznowi nagrzewanie.

- Nie wolno demontować urządzenia ani zmieniać jego obwodów bez zgody producenta. Zamiast tego używaj wyłącznie zalecanych części elektronicznych. Samodzielne przeróbki mogą spowodować zwarcie i uszkodzenie urządzenia.
- Trzymaj urządzenie z dala od dzieci, zwierząt domowych i roślin podczas jego pracy.
- Kranik posiada funkcję grzania, a jego powierzchnia nagrzewa się podczas pracy. Zabrania się dotykania metalowej części kranika rękami w trakcie pracy lub bezpośrednio po jej zakończeniu, aby uniknąć poparzeń.
- Aby zapewnić bezpieczną instalację i użytkowanie pieca do topienia wosku, dolna płyta szafki (na której używany jest piec) musi być gładka i płaska. Dno urządzenia musi być stabilnie zamocowane, aby zapobiec wywróceniu się urządzenia i rozlaniu wosku.
- Ze względu na to, że czujnik temperatury jest zainstalowany na spodzie płyty grzewczej, tolerancja temperatury w urządzeniu wynosi $\pm 10^{\circ}\text{C}$.

PRZEGLĄD PRODUKTU



Zakres temperatury
50-100°C/122-212°F

PRZYGOTOWANIE

1. Uwagi:

(1) Urządzenie musi być używane w pomieszczeniach i powinno być ustawione na stabilnej platformie lub stojaku. Tył urządzenia powinien być oddalony o co najmniej 10 cm od ściany. Trzymaj urządzenie z dala od ścian.




(2) Nie włączaj urządzenia bez dodania wosku, ponieważ może to uszkodzić urządzenie lub spowodować inne zagrożenia.



(3) Świece mają różne temperatury topnienia. Ustaw odpowiednią temperaturę grzania w zależności od rodzaju wosku i jego punktu topnienia. W przeciwnym razie temperatura może być zbyt wysoka, co doprowadzi do przypalenia wosku.

(4) Przykrywaj urządzenie pokrywką podczas używania, aby uniknąć poparzeń.

(5) Poziom ochrony tego urządzenia dla elementów pod napięciem to Klasa I. Wtyczka zasilająca musi być wyposażona w trzybolcowe gniazdo z niezawodnym uziemieniem ochronnym i wyłącznikami różnicowoprądowymi.



2. Wyjaśnienie wskaźników

- Czerwone światło (Heating): Urządzenie nagrzewa się.
- Żółte światło (Insulation): Urządzenie znajduje się w stanie podtrzymywania ciepła. Gdy temperatura spadnie, urządzenie automatycznie zacznie się ponownie nagrzewać.
- Zielone światło (Standby): Urządzenie automatycznie wyłącza zasilanie i wykorzystuje pozostałe ciepło do dalszego topienia wosku.



KROKI TWORZENIA ŚWIEC

1. Podłącz przewód zasilający i włącz urządzenie. Sprawdź, czy czerwony wskaźnik grzania działa prawidłowo. Następnie wyłącz przełącznik urządzenia. Upewnij się, że wewnątrz pieca nie ma wilgoci.



2. Załóż rękawice ochronne i odpowiednie ubranie. Podczas pracy zabronione jest noszenie krótkich spodni i spódnic. Trzymaj dzieci i zwierzęta z dala od urządzenia.



3. Dodaj wosk do pieca. Upewnij się, że poziom wosku przekracza 2 cm od dna, ale nie przekracza maksymalnego poziomu zaznaczonego linią MAX.

4. Włącz przełącznik zasilania i ustaw temperaturę o 5-10°C wyższą niż punkt topnienia wosku.

Przykład: Punkt topnienia wosku pszczelego to 62-67°C. Ustaw temperaturę na 70°C.



5. Urządzenie zacznie się nagrzewać. Podczas procesu grzania przykryj urządzenie pokrywką. Co 30-50 sekund mieszaj wosk łyżką przez 3-4 sekundy.



6. Podczas grzania, aby zapobiec przypaleniu się wosku, urządzenie automatycznie zatrzyma grzanie w przypadku zbyt wysokiej temperatury. Gdy temperatura spadnie, urządzenie automatycznie ponownie się nagrzeje, aby utrzymać odpowiedni poziom ciepła.

7. Gdy воск zostanie całkowicie stopiony, wyłącz zasilanie. Użyj miarki lub foremki na воск, aby nalać płynny воск z kranika urządzenia.



8. Jeśli chcesz, aby Twoja świeca miała przyjemniejszy zapach, możesz dodać olejki zapachowe.



9. Jeśli chcesz stworzyć bardziej kolorowe świece, możesz dodać suszone kwiaty lub barwniki według własnego uznania. Po tym należy poczekać 24 godziny na stężenie wosku i wyjęcie go z formy (uwaga: nie używaj zbyt dużo siły przy wyjmowaniu, ponieważ воск może nie być całkowicie utwardzony).




10. Przerwa w używaniu urządzenia:
Gdy urządzenie nie jest używane, zamknij kranik, odłącz urządzenie od zasilania i przechowuj je w suchym miejscu o temperaturze pokojowej.

11. Praktyczne wskazówki:
Po stopieniu wosku należy od razu przelać do formy, aby wykonać gotowy produkt. Jeśli воск pozostanie w urządzeniu przez dłuższy czas, może zmienić kolor i wpłynąć na jakość świecy.

ROZWIĄZYWANIE PROBLEMÓW

OBJAW USTERKI	PRZYCZYNA PROBLEMU	SPOSÓB USUNIĘCIA
Światło się nie świeci	1. Wskaźnik świetlny jest uszkodzony. 2. Obwód wskaźnika świetlnego jest odłączony.	1. Wymień wskaźnik świetlny. 2. Napraw odłączony przewód.
Wskaźnik grzania jest włączony, ale temperatura wosku nie rośnie	Brak fazy zasilania lub przepalony bezpiecznik.	1. Wymień termostat. 2. Podłącz przewód uziemiający.
Gdy temperatura wosku osiąga ustawioną wartość, światło pracy nie gaśnie	Uszkodzony termostat.	Wymień termostat.
The body has induced voltage	Nieuziemiający przewód lub słaby kontakt przewodu uziemiającego.	Podłącz przewód uziemiający.

SCHEMAT OBWODU PRODUKTU



Pytania i odpowiedzi (Q&A)

P: Jak wyczyścić topielnik wosku?

Odpowiedź:

1. Proste czyszczenie: Po użyciu wytrzyj cały wosk w wiadrze czystym ręcznikiem, zanim stwardnieje. (Podczas pracy należy zachować ostrożność, aby uniknąć poparzeń).
2. Pełne czyszczenie: Gdy płynny wosk zostanie całkowicie wylany, napełnij wiadro wodą (nie przekraczając linii MAX), włącz urządzenie i ustaw termostat na 70 stopni. Po osiągnięciu ustawionej temperatury wyłącz zasilanie i rozpocznij czyszczenie. Dodaj odpowiednią ilość kwasu cytrynowego lub białego octu do pieca do topienia wosku, użyj ściereczki do wycierania i drewnianego patyczka, aby oczyścić ściany wiadra i dno. Następnie spuść wodę z kranika, osusz wiadro suchym ręcznikiem i ponownie wyczyść wnętrze. Gdy dno wiadra będzie suche, zamknij pokrywę, odłóż urządzenie i poczekaj na kolejne użycie. (Podczas całego procesu czyszczenia należy nosić rękawice odporne na wysoką temperaturę, aby zapobiec poparzeniom i uniknąć przewrócenia urządzenia).

P: Ile wosku sojowego można stopić jednocześnie?

Odpowiedź:

1. WMF-5L: Można stopić do 1,65 kg wosku jednorazowo (70% maksymalnej pojemności).
2. WMF-8L: Można stopić do 3,5 kg wosku jednorazowo (70% maksymalnej pojemności).
3. WMF-15L: Można stopić do 7 kg wosku jednorazowo (70% maksymalnej pojemności).

P: Czy stopiony wosk może być przechowywany w topielniku?

Odpowiedź:

Nie zaleca się pozostawiania wosku w urządzeniu na noc, aby zapobiec zestaleniu i zabrudzeniu wosku, co może wpłynąć na funkcję grzewczą elementu grzewczego w komorze. Jeśli wosk zastygnie w topielniku, czas ponownego topienia się wydłuży. Topielnik został wyposażony w system ochrony przed podgrzewaniem bez wosku i podgrzewany kranik, aby zapobiec przypaleniu wosku lub zatkanie kranika.

Polski

P: Dlaczego podczas pracy, gdy światło grzania (Heating) zmienia się na zielone (Standby), воск jeszcze się nie roztopił?

Odpowiedź:

Aby zapobiec przypaleniu wosku, urządzenie zostało wyposażone w system ochrony przed podgrzewaniem bez wosku. Gdy temperatura dna urządzenia osiągnie ustawioną wartość, kontroler automatycznie przełączy się w tryb zatrzymania grzania i wykorzysta pozostałe ciepło do topienia wosku. Po kilku minutach, gdy temperatura spadnie, urządzenie ponownie zacznie się nagrzewać, a wskaźnik grzania (czerwone światło) włączy się.

OŚWIADCZENIE PRAWNE

1. Podczas pracy należy nosić sprzęt ochronny, aby zapobiec poparzeniom.
2. Zdjęcia na stronie internetowej są jedynie poglądowe, obowiązują rzeczywiste produkty w danej dostawie. Produkty dostarczane przez różne kanały dystrybucji w różnych regionach mogą się nieznacznie różnić, a produkty widoczne w sklepie mają charakter wiążący.
3. Wzór opakowania produktu może ulec zmianie bez wcześniejszego powiadomienia, a zdjęcia w sklepie będą aktualizowane w miarę możliwości, aby zapewnić najnowsze typy produktów.
4. Nasz topielnik wosku posiada certyfikaty CE, FCC, Rohs, UKCA. Jest normalne, że podczas topienia wosków wyczuwalny jest zapach wosku.
5. Zabronione jest rozbieranie wewnętrznych obwodów i elementów tego produktu bez zgody producenta lub zastępowanie części innymi niż te dostarczane przez firmę. W przeciwnym razie firma nie ponosi odpowiedzialności za uszkodzenie produktu.
6. Dla wszystkich sprzedawanych produktów obowiązuje wymóg przestrzegania ścisłych zasad montażu oraz stosowania odpowiedniej technologii modelowej. Producent ponosi odpowiedzialność wyłącznie za obsługę posprzedażową zakupionego produktu (sam produkt, w przypadku jego naprawy lub wymiany). Producent potwierdza, że nie ponosi odpowiedzialności za problemy z jakością, inne straty lub uszkodzenia.
7. Zaleca się zdobycie niezbędnej wiedzy oraz porad od innych. Zdecydowanie sugerujemy, aby wszyscy nabywcy zdobyli podstawową wiedzę na temat instalacji urządzenia, jego konfiguracji i obsługi pod nadzorem doświadczonych użytkowników.
8. Urządzenie musi być używane w stabilnym i bezpiecznym miejscu, z dala od ryzyka przewrócenia. Maszynę należy również trzymać z dala od dzieci i zwierząt podczas użytkowania.
9. Produkt jest przeznaczony wyłącznie do legalnych zastosowań. Bez pisemnej zgody producenta i przedstawiciela handlowego nikt nie może używać tego produktu w celach komercyjnych. Nie wolno go używać do celów politycznych, religijnych, wojskowych ani innych specjalnych i nielegalnych działań.
10. Produkt do topienia wosku, w tym jego projekt, produkcja i sprzedaż, nie są związane z jakąkolwiek propagandą polityczną, wojskową, religijną, krajową, rasową ani dotyczącą koloru skóry. Celem producenta jest szacunek dla nauki, przestrzeganie zasad historycznych i wspieranie pokoju na świecie.

Pozostałe kwestie nieobjęte niniejszym rozporządzeniem będą wdrażane zgodnie z odpowiednimi przepisami prawa krajowego i regulacjami!

SPECYFIKACJA

Model	WMF-5L	WMF-8L	WMF-15L
Pojemność	5L	8L	15L
Napięcie znamionowe	AC 120V; 60HZ (Stany Zjednoczone)		
	AC 230V; 50HZ (Wielka Brytania/Niemcy)		
Materiał wiadra	Stal nierdzewna		
Moc znamionowa	1100W		
Zakres temperatur	50°C-100°C(122°F-212°F)		

Napięcie (AC 120V/60Hz lub AC 230V/50Hz) produktu zależy od Twojego zamówienia.

4. Logo WEEE (utyliczacja):

Produkt spełnia wymagania Dyrektywy dotyczącej zużytego sprzętu elektrycznego i elektronicznego (WEEE) oraz ściśle przestrzega odpowiednich regulacji.



Warranty Terms:

- 1.The table for feedback from customers should be returned to our company within a month after the date of purchase.In this way,customers may enjoy one-month repair warranty.
- 2.Repair Warranty and Purchase Certificate should be presented.The warranty only applies when all the required documents are available.
- 3.The warranty does not apply when the equipment has received damage through abuse,carelessness,improper installation,accident or mishandling during shipment,connecting to improper line voltage,or has been serviced by anyone other than an authorized factory representative.
- 4.After the warranty period,we are ready to provide charged repair service,perfect as always.

Dear Sir / Madam:

Thank you for purchasing our products.' To improve our service and ensure the proper use of our products,please kindly write down your suggestions.

Name of Product: _____

Date of Purchase: _____

Your Suggestions: _____

Package: _____

Functions: _____

Others: _____

Date : _____

GUARANTEE CARD

The product conforms to the technical standards

QC. _____

Manufacture Date _____

GUARANTEE CARD

The warranty is valid in one year since the purchase of this ,any quality problem found,please send back to us with courier fee to be collected,upon receipt of the returning unit,we will repair it and send back to customer within two working days.

Notice:Please enclose the warranty card along with the returning product, or else we have the right to reject the repairing,thanks for your corporation.